

Pipette services

Avantor Services effectue des étalonnages de pipettes indépendants du fournisseur selon les normes ISO les plus strictes (ISO17025 et ISO8655).

Ceci garantit que vos pipettes répondent aux normes.

Avantor Services peut effectuer des étalonnages sur toutes les marques de pipettes.



	VWR® Care	VWR® Light	VWR® Eco	VWR® Classic	VWR® Classic	VWR® Classic	VWR® Pro	VWR® Compliant
	Preventative maintenance by experts	Economic calibration and adjustment	Preventative maintenance, economic calibration and adjustment	Standard calibration and adjustment	Preventative maintenance, standard calibration and adjustment	AS-FOUND standard calibration, Preventative maintenance, AS-LEFT standard calibration and adjustment	Preventative maintenance, standard calibration and adjustment	AS-FOUND standard calibration, Preventative maintenance, AS-LEFT standard calibration and adjustment
As-found calibration								
Standard calibration (mono channel 2 volumes min., max. with 10 measurements) (multi channels 2 volumes min., max. with 5 measurements)						•		
As found calibration according ISO 8655 (3 volumes with 10 measurements)								•
Checking against ISO 8655 specifications						•		•
Calibration report ISO 17025						•		•
Preventative maintenance								
Disassembling the pipette and check on worn/defective parts	•		•		•	•	•	•
Professional cleaning of internal and external parts	•		•		•	•	•	•
Lubrication of seal, O-rings and piston if applicable	•		•		•	•	•	•
Assembling the pipette	•		•		•	•	•	•
Leak functional testing	•		•		•	•	•	•
As-left calibration								
Quick calibration (2 volumes min., max with 4 measurements)		•	•					
Standard calibration (mono channel 2 volumes min., max. with 10 measurements) (multi channels 2 volumes min., max. with 5 measurements)				•	•	•		
As Left calibration according ISO 8655 (3 volumes with 10 measurements)							•	•
Checking against ISO 8655 specifications		•	•	•	•	•	•	•
Calibration report ISO 17025		•	•	•	•	•	•	•
Adjustment and recalibration when needed		•	•	•	•	•	•	•
Calibration report after adjustment		•	•	•	•	•	•	•

Contact Avantor Services to schedule a maintenance or calibration or for more information about our services:
technical.service.be@avantorsciences.com

VWR International bv
 Researchpark Haasrode 2020 - Geldenaaksebaan 464 - 3001 Leuven
 cedex | t +32 (0) 16 385 011 | vwr.be@vwr.com | be.vwr.com